SD card defective in Lenovo T430 Posted by lenovoadmin - 06 Jan 2017 08:57

It seems to be a very starightforward socket replacement. The socket is soldered to a replaceable board and the board is screwed to the housing. Sadly there is not an ifixit manual but I'm sure you can find something online.
