

## Battery guage disappeared from taskbar

Posted by lenovoadmin - 06 Jan 2017 11:55

---

Could you right click the taskbar[in a blank area] and select Toolbars and see if any battery gauge shows up?

=====